COMPLETION REPORT

1	Name of the work	Reserve fund for emergency work Construction of RCC deck at Manjunatha Nagara, difence Colony, Soundarya Layout, Mallasandra (opp. Arunodaya Hospital) in Ward No. 14 Bagalagunte
2	Sanctioned Estimate No. & Date	ಮುಖ್ಯ ಅಭಿಯಂತರರು ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
3	Head of Account which is chargeable	
4	Instrument Order NO. & Date	
5	Name Of Contractor	Technical Manager (west) Karnataka Rural Infrastructure Development Limited, Project Implementation unit, Madhavanagara Bangalore 560 001.
6 a	Time Stipulated for Completion of work	
b	Delay in Exculpation of Work	—
7	Measurement recorded in	
8	Check Measurement of the Asst	
9	Name of the office/official in charge of the work	
10	a) Asst. Eng/junior Eng	
	b) Asst. Exe Engineer	

Sanctioned Estimate Amout	Amout Claims As per Actually Vide As per bills	Excess	Savings
		—	

1) Certified that the above work has been completed within the stipulated time noted in the
2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
3) Certified that the above work has been executed by the contractor satisfactory in

ASSISTANT ENGINEER.

ASSIATANT EXECUTIVE ENGINEER

ಕ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಮಲ್ಲಸಂದ್ರ, ಬೆಂಗಳೂರು - 560 073

EXECUTIVE ENGINEER

ಮುಖ್ಯ ಅಭಿಯಂತರರು
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

Bruhat Bangalore Mahanagara Palike,